

Activity Type	SF2	Safety Inspection (Walked)	Survey	013083
Address	HIGH STREET EAST			
	WALLSEND			
Date Due	06/04/2018			
Frequency	1	Months	Standard Frequency	No Frequency
Done Date/Time	06/04/2018	09:19	☒ Mark Activity as Complete?	
Inspector	IVOR	Ivor Steinberg (Highway Maintenance)		
Next Due Date	06/05/2018	(Blank = Calculated) Next Done Date04/05/2018		
Highway Ins	Action Required	Gully/Drainage		
Signage	No Action	Lines		
Description				

L.A.Code

00305046

Stage

COMPLETED

Source

HAND-HELD

Class

3

☒ T/S

☐ P/S

☐ L/R

Address

HIGH STREET EAST

Unit Type

☐ E/D

☐ S/R

☐ Oth

Section

WALLSEND

Unit No.

☒ Permit?

Location

o/s your move, lyndhurst furn, junc n'land st, o/s

Network

UKPMS

Chainage Display

Address

Chainage

0.00

XSP

Grid Ref.

Activity Type

SF2

Safety Inspection (Walked)

Contract

REAC/1

Reactive Maintenance

Defect

RW01

Flexible Carriageway

☐ SWR Link?

Exp Code

CS/095201 - 01

Year

18

Priority

2

10 days

Charge Method

S/C

Version

2

Client Ref.

Duration

0

Planned Start

Planned Finish

Originated

06/04/2018 09:20

IVOR

Latest Cost

56.84

Last Inspection Type

Date

Selected

06/04/2018 14:59

IVOR

Contractor

HIGHWAY OPS

Next Inspection Type

Date

Ordered

06/04/2018

JADEB

Order Number

00077167

Completed

18/04/2018 14:20

LAURAT

Action Type

DEF

Default Action

Action Text

Description

NO PERMIT REQUIRED, potholes

L.A.Code00305046StageCOMPLETED

AddressHIGH STREET EAST
WALLSEND

SourceHAND-HELDClass3

Unit Type

Unit No.

NetworkUKPMS

Chainage0.00

Chainage DisplayAddress

Chainage Grid Ref.

☒ T/S☐ P/S☐ L/R

☐ E/D☐ S/R☐ Oth

☒ Permit?

Add Line

New Item

Amend Line

Delete Line

View Add-Ons

Copy SOR

View Line

Contract IdREAC/1DefectRW01Flexible Carriageway

Current Item1Locationo/s amanda glen hair studio

L.A.Code DiscountingL.A.Code Add-ons

SOR Version2

Change Version

☐ Show Locations only?

Item	Location	Schedule	Name	Unit	Quantity	Value
1	o/s amanda glen hair studio					
1.1		27	Pothole repair	NUM	1.00	14.21
2	junc nothumberland st					
2.1		27	Pothole repair	NUM	1.00	14.21
3	o/s lyndhurst furniture					
3.1		27	Pothole repair	NUM	1.00	14.21
4	o/s your move					
4.1		27	Pothole repair	NUM	1.00	14.21

L.A.Code

00305043

Stage

COMPLETED

Address

HIGH STREET WEST

WALLSEND

Section

Location

o/s kfc

Source

HAND-HELD

Class

3

☒ T/S

☐ P/S

☐ L/R

Unit Type

FOOTWAY

☐ E/D

☐ S/R

☐ Oth

Unit No.

☒ Permit?

Network

UKPMS

Chainage Display

Address

Chainage

0.00

XSP

Grid Ref.429809.74 566324.81

Activity Type

SF2

Safety Inspection (Walked)

Contract

REAC/1

Reactive Maintenance

Defect

RW05

Modular Footway

☒ SWR Link?

Exp Code

CS/095201 - 05

Year

18

Priority

2

10 days

Charge Method

S/C

Version

2

Client Ref.

Duration

1

SWR Earliest Start

19/04/2018

SWR Latest End

23/04/2018

Application Status

Granted

17/04/2018

Ref

HY002G-HIGH-00305043.2.2

Originated

06/04/2018

11:18

IVOR

Latest Cost

338.83

Last Inspection Type

Date

Selected

06/04/2018

14:58

IVOR

Contractor

HIGHWAY OPS

Next Inspection Type

Date

Ordered

06/04/2018

JADEB

Order Number

00077164

Completed

19/04/2018

DSTO0805

Action Type

DEF

Default Action

Action Text

Description

Renew/relay repair to modular footway

L.A.Code00305043

StageCOMPLETED

SourceHAND-HELD

Class3

☒ T/S

☐ P/S

☐ L/R

AddressHIGH STREET WEST

Unit TypeFOOTWAY

☐ E/D

☐ S/R

☐ Oth

SectionWALLSEND

Unit No.

☒ Permit?

NetworkUKPMS

Chainage DisplayAddress

Locationo/s kfc

Chainage0.00

XSP

Grid Ref.429809.74 566324.81

Add Line

New Item

Amend Item

Delete Line

View Add-Ons

Copy SOR

View Line

Contract IdREAC/1

DefectRM05

Modular Footway

Current Item1

Locationo/s kfc l&r 2x v70s, l&d 5x 6x5 b/n kerbs

SOR Version2

Change Version

L.A.Code DiscountingL.A.Code Add-ons

☐ Show Locations only?

Item	Location	Schedule	Name	Unit	Quantity	Value
1	o/s kfc l&r 2x v70s, l&d 5x 6x5 b/n kerbs					
1.1		16	Lift & relay flagged footway	M2	0.54	16.88
1.2		11	Provide new and lay kerb on ext: M	M	5.00	321.95